

State of Utah

Department of Natural Resources

MICHAEL R. STYLER Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA
Division Director

GARY R. HERBERT Lieutenant Governor

Representatives Present During the Inspection:						
Company	Dennis Ware Controller					
OGM	Steve Demczak Environmental Scientist III					

4

Inspection Report

Permit Number:	C0070006		
Inspection Type:	PARTIAL		
Inspection Date:	Monday, March 16, 2009		
Start Date/Time:	3/16/2009 10:00:00 AM		
End Date/Time:	3/16/2009 12:00:00 PM		
Last Inspection:	Monday, February 09, 2009		

Inspector: Steve Demczak, Environmental Scientist III

Weather: <u>Sunny, snow covered, 40's</u> InspectionID Report Number: <u>1945</u>

Accepted by: jhelfric

3/24/2009

Permitee: PLATEAU MINING CORP
Operator: PLATEAU MINING CORP

Site: STAR POINT MINE

Address: PO BOX 30, HELPER UT 84526-0030

County: CARBON

JON M. HUNTSMAN, JR. Governor

Permit Type: PERMANENT COAL PROGRAM

Permit Status: RECLAIMED

Current Acreages

8,919.91	Total Permitted		
113.34	Total Disturbed		
113.34	Phase I		
	Phase II		
	Phase III		

Mineral Ownership

Types of Operations

✓ Federal
✓ Underground

✓ State
Surface

County
Loadout

✓ Fee
Processing

Other
Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

No violations were issied.

Inspector's Signature:

Steve Demczak, Environmental Scientist III

Date

Monday, March 16, 2009

Inspector ID Number: 39

Permit Number: C0070006 Inspection Type: PARTIAL

Inspection Date: Monday, March 16, 2009

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- Substantiate the elements on this inspection by checking the appropriate performance standard.
 For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
- b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	✓		✓	
2.	Signs and Markers				
3.	Topsoil	✓		✓	
4.a	Hydrologic Balance: Diversions	✓		✓	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments		✓		
4.c	Hydrologic Balance: Other Sediment Control Measures	✓		V	
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives		✓		
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments		V		
8.	Noncoal Waste	V		✓	
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage	✓		V	
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading	✓		✓	
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.a	Roads: Construction, Maintenance, Surfacing		✓		
16.Ł	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations	V		~	
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Permit Number: C0070006 Inspection Type: PARTIAL

Inspection Date: Monday, March 16, 2009

Page 3 of 3

1. Permits, Change, Transfer, Renewal, Sale

The DOGM permit will expire on Jan. 28, 2012.

3. Topsoil

All topsoil was used in reclamation.

4.a Hydrologic Balance: Diversions

Some of the diversions were snow covered. The diversions that had no snow were open and would function was designed.

4.c Hydrologic Balance: Other Sediment Control Measures

The disturb area is pocked to control sediment runoff.

8. Noncoal Waste

No non-coal waste was seen during the inspection.

10. Slides and Other Damage

No slides or other damage was noticed during the inspection. Roads were snow covered.

12. Backfilling And Grading

The disturb area was backfilled and graded.

18. Support Facilities, Utility Installations

There are no facilities.